

SPECIFICATION PACKAGING MARKINGS

Specification packaging markings must be located on an unobstructed, non-removable part of the packaging. The letters and numerals that identify the packaging specifications must be stamped, embossed, burned or printed on the packaging.

Manufacturer's markings must include, in the following order:

1. UN symbol
2. Packaging code
3. Performance level
4. Gross mass or specific gravity
5. Solids or inner packaging, or hydrostatic test pressure
6. Year of manufacture
7. Country of authorization and markings
8. Manufacturer symbol or name and address
9. Minimum thickness (intended for reuse or reconditioning)

